

Doc.-Number	Name	Issue	Date	Model	Serial-Numbers	Applicability											Remarks
						EASA	UK	Canada									
Supplement to aircraft maintenance manuals																	
---	Ergänzung B – VHF-Antenne im Seitenruder (German)	---	01.11.2022	AS 33 Me	all	X										For aircraft with optional radio antenna in the rudder	
	Supplement B – VHF antenna in the rudder (English)					X	X	X									
Aircraft repair manuals																	
---	Reparaturhandbuch (German)	---	13.04.1999	AS 33 Me	all	X											
---	Repair manual (English)	---	13.04.1999	AS 33 Me	all	X	X	X									
Supplement to aircraft repair manuals																	
---	Technische Mitteilung Nr. 01-99 für alle Flugzeugmuster in Faserverbundbauweise (German)	---	12.03.1999	AS 33 Me	all	X											
	Technical note No. 01-99 for all aircraft types of glass fiber & fiber composite construction (English)					X	X	X									
---	Technische Mitteilung Nr. 03-99 für alle Flugzeugmuster der ASH, ASK & ASW-Baureihen (German)	---	26.03.1999	AS 33 Me	all	X											
	Technical note No. 03-99 for all aircraft of the production series ASH, ASK & ASW (English)					X	X	X									

Doc.-No. 335-99-0001-00 Issue: 04 Date: 20.06.2024 Page: 7 of 11	List of applicable publications	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	AS 33 Me	

Section C: Service bulletins

Doc.-Number	Name	Issue	Date	Applicability												categorisation ¹	manual rev. ²	urgency	Remarks
				Model	Serial No.	EASA	UK	Canada											
Type-specific service bulletins																			
AS 33 Me TN No. 1	Alternative Batteriezellen für Antriebsbatterie (German)	---	01.11.2022	AS 33 Me	all	X											O	AFM AMM	none
	Alternative battery cells for the propulsion battery (English)					X	X	X											
AS 33 Me TN No. 2	Ergänzung Wartungshandbuch (German)	---	07.08.2023	AS 33 Me	all	X											M	AFM AMM	31.12.2023
	Revision of the maintenance manual (English)					X	X	X											
335.99.0002	AS 33 Me - TM 3 Gültige Software-Versionen (German)	00	01.11.2023	AS 33 Me	all	X											M	---	none
	AS 33 Me - TN 3 Approved software versions (English)					X	X	X											

¹ M = Mandatory, R = Recommended, O = Optional

² AFM = Revision of Flight Manual, AMM = Revision of Maintenance Manual, -Sup = New supplement to AFM / AMM

Doc.-Number	Name	Issue	Date	Model	Serial No.	Applicability										categorisation ¹	manual rev. ²	urgency	Remarks	
						EASA	UK	Canada												
General service bulletins																				
TM Nr. 01-2005	Verwendung von Hart-schaumstoff gemäß Werkstoff-Leistungsblatt 5.1460.2 (German)	---	24.02.2005	AS 33 Me	all	X	X	X									O	---	none	
TN No. 2-2005	Anerkannte Reparaturverfahren nach EU-VO 1702/2003, Teil 21, Abschnitt M (German)	---	24.05.2005	AS 33 Me	all	X											O	---	none	
	Approved repair procedures according to EU-VO 1702/2003, Part 21, section M (English)					X	X	X												
TN No. 02-2008	Anweisung für den Einbau von Ausrüstung (German)	04	21.02.2023	AS 33 Me	all	X											O	---	none	
	Instruction for the installation of equipment (English)					X	X	X												
TN No. 02-2013	Verwendung von Pyrofil TR30S- 3K (German)	03	21.02.2023	AS 33 Me	all	X											O	---	none	
	Usage of Pyrofil TR30S-3K (English)					X	X	X												

Doc.-No. 335-99-0001-00 Issue: 04 Date: 20.06.2024 Page: 10 of 11	List of applicable publications	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	AS 33 Me	

Section D: Service information

Doc.-Number	Name	Issue	Date	Applicability												categorisation ³	manual rev. ⁴	urgency	Remarks	
				Model	Serial No.	EASA	UK	Canada												
99.090.9028	Arbeitsanweisung "Einbau Flarmantenne hinter FW-Klappe" (German)	D	05.01.2023	AS 33 Me	all	X	X	X									O	--	none	

³ M = Mandatory, R = Recommended, O = Optional

⁴ AFM = Revision of Flight Manual, AMM = Revision of Maintenance Manual, -Sup = New supplement to AFM / AMM

Doc.-No. 335-99-0001-00 Issue: 04 Date: 20.06.2024 Page: 11 of 11	List of applicable publications	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	AS 33 Me	

Section E: Notes

1. For countries not listed in the tables the owner/operator of the aircraft has to check the applicability of the respective Manual/Service-Bulletin/Service-Info based on the national legal regulations.
2. Mandatory and recommended Service-Bulletins or Service-Information has to be followed by the owner/operator of the aircraft. Non-compliance leads to exclusion of any liability.
3. The applicability of Revisions or Supplements to approved manuals (Flight / Maintenance / Repair) depends on the configuration of the aircraft and has to be checked for each individual serial number.

Section F: Change Record

Issue	Date	Changes
00	29.08.2023	Initial issue
01	29.08.2023	Hyperlinks added
02	02.11.2023	Maintenance instructions 340.99.0002 and 340.99.0003 added; service bulletin 335.99.0002 added
03	06.03.2024	UK added
04	20.06.2024	Canada added