

Section C: Service bulletins

Doc.-Number	Name	Issue	Date	Applicability												categorisation ¹	manual rev. ²	urgency	Remarks
				Model	Serial No.	EASA	Australia												
Type-specific service bulletins																			
AS 34 Me TN No. 1	Alternative Batteriezellen für Antriebsbatterie (German)	---	01.10.2022	AS 34 Me	all	X	-										O	AFM AMM	---
	Alternative battery cells for the propulsion battery (English)					X	X												
AS 34 Me TN No. 2	Schwerpunktkupplung (German)	---	22.03.2023	AS 34 Me	all	X	-										O	AMM Sup	none
	C.G.-hook (English)					X	X												
AS 34 Me TN No. 3	Ergänzung Wartungshandbuch (German)	---	07.08.2023	AS 34 Me	all	X	-										M	AMM	31.12.2023
	Revision of the maintenance manual (English)					X	X												
340.99.0004	AS 34 Me - TM 4 Gültige Software-Versionen (German)	00	01.11.2023	AS 34 Me	all	X	-										M	---	none
	AS 34 Me - TN 4 Approved software versions (English)					X	X												

¹ M = Mandatory, R = Recommended, O = Optional
² AFM = Revision of Flight Manual, AMM = Revision of Maintenance Manual, -Sup = New supplement to AFM / AMM

Doc.-No.
340-99-0001-00
 Issue: 04
 Date: 05.07.2024
 Page: 8 of 11

List of applicable publications

AS 34 Me



Alexander Schleicher GmbH & Co.
Segelflugzeugbau

Alexander-Schleicher-Straße 1
 D-36163 Poppenhausen
 (Wasserkuppe)

Doc.-Number	Name	Issue	Date	Model	Serial No.	Applicability										categorisation ¹	manual rev. ²	urgency	Remarks
						EASA	Australia												
340-99-0005-00	AS 34 Me – TM 5 Sicherung des Triebwerks- instruments (German)	00	21.05.2024	AS 34 Me	all	X	-									M	AMM	at the next scheduled maintenance action	
	X					X													
General service bulletins																			
TM Nr. 01-2005	Verwendung von Hart- schaumstoff gemäß Werk- stoff-Leistungsblatt 5.1460.2 (German)	---	24.02.2005	AS 34 Me	all	X	X									O	---	none	
TN No. 02-2005	Anerkannte Reparaturver- fahren nach EU-VO 1702/2003, Teil 21, Ab- schnitt M (German)	---	24.05.2005	AS 34 Me	all	X	-									O	---	none	
	Approved repair proce- dures according to EU-VO 1702/2003, Part 21, sec- tion M (English)					X	-												
TN No. 02- 2008	Anweisung für den Einbau von Ausrüstung (German)	04	21.02.2023	AS 34 Me	all	X	-								O	---	none		
	Instruction for the installa- tion of equipment (English)					X	X												
TN No. 02- 2013	Verwendung von Pyrofil TR30S- 3K (German)	03	21.02.2023	AS 34 Me	all	X	-								O	---	none		

Doc.-No. 340-99-0001-00 Issue: 04 Date: 05.07.2024 Page: 10 of 11	List of applicable publications	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	AS 34 Me	

Section D: Service information

Doc.-Number	Name	Issue	Date	Applicability											categorisation ³	manual rev. ⁴	urgency	Remarks		
				Model	Serial No.	EASA	Australia													
99.090.9028	Arbeitsanweisung "Einbau Flarmantenne hinter FW-Klappe" (German)	D	05.01.2023	AS 34 Me	all	X	X										O	--	none	

³ M = Mandatory, R = Recommended, O = Optional

⁴ AFM = Revision of Flight Manual, AMM = Revision of Maintenance Manual, -Sup = New supplement to AFM / AMM

Doc.-No. 340-99-0001-00 Issue: 04 Date: 05.07.2024 Page: 11 of 11	List of applicable publications	 Alexander Schleicher GmbH & Co. Segelflugzeugbau Alexander-Schleicher-Straße 1 D-36163 Poppenhausen (Wasserkuppe)
	AS 34 Me	

Section E: Notes

1. For countries not listed in the tables the owner/operator of the aircraft has to check the applicability of the respective Manual/Service-Bulletin/Service-Info based on the national legal regulations.
2. Mandatory and recommended Service-Bulletins or Service-Information has to be followed by the owner/operator of the aircraft. Non-compliance leads to exclusion of any liability.
3. The applicability of Revisions or Supplements to approved manuals (Flight / Maintenance / Repair) depends on the configuration of the aircraft and has to be checked for each individual serial number.

Section F: Change Record

Issue	Date	Changes
00	24.08.2023	Initial issue
01	29.08.2023	Structure updated
02	29.08.2023	Links added
03	02.11.2023	Service bulletin 340.99.0004, maintenance instructions 340.99.0002 and 340.99.0003 added
04	05.07.2024	Service bulletin 340-99-0005-00 and section F "Change Record" added