Page 1 of 2			ASH 2 echnical 1 No. 9 Issu	Note		Alexander Schleicher GmbH & Co. Segelflugzeugbau D - 36163 Poppenhausen	
Subject: Applicability: Classification: Urgency: Reason:	ASH 2 Minor option	Alternative hydraulic wheel brake system TOST ASH 26 ; Type-Certificate LBA 383; all serial numbers Minor Change optional Product improvement					
Action:	Excha	Exchange of the following parts of the wheel brake system:					
			current se	eries standard	alter	native	
	Master Cylinder		Cleveland	10-20		TOST HBZS f. MIL-H m. NPT, P/N 050305	
			260.23.00 (to Reserv	52 Brake Hos /oir)		23.0053 Brake Hose (to ervoir) *)	
	Whe	el Brake Cylinder	Cleveland	30-9		TOST BZT2 5L f. MIL-H m. NPT, P/N 080203	
	*) During assembly it might be necessary to relocate the FRP retaining clamp.						
	 tilation stay the same. Also the maintenance and operation is in general unchanged be- tween the alternative and the current version. More detailed information can be found in the Operating Manual for TOST wheel brake: "Component Maintenance Manual CMM 013" and the "Instruction for filling and bleeding hydraulic disk brake systems" from TOST. Both documents must be included in the appendix of the maintenance manual. It is also possible to exchange only parts of the wheel brake, means to combine the existing master cylinder with an alternative wheel brake cylinder or vice versa. Note: It is recommended to use a filling pump or vacuum filling device (e.g. TOST P/N 059300 / 059330) for an easier filling or bleeding. Exchange or change of the following manual pages: 						
	г	enance Manual: Model / Variant	TN	Issue	Daga		
		ASH 26	TN 9	01.02.17	Page 2.39		
	All pages have to be changed as follows: Add the text "alternatively TOST wheel brake cylinder 080203 and/or TOST master cylinder 050305" underneath the existing text "Cleveland wheel brake cylinder 30-9 and master cylinder 10-20". Fill in the TN and issue according to the table above in the field "Revision" in the footer.						
Material and Drawings:	See Action						
Mass and Balance:	The change in mass and C. of G. position is negligible.						

2 of 2

ASH 26 Technical Note No. 9 Issue II

Notes:

The actions have to be considered as a non-complex maintenance task regarding aviation law. The respective regulations must be applied.

The exchange of the pages has to be noted in the record of revision of the manual. The list of effective pages must be updated, too.

Poppenhausen, 12.06.2024

Alexander Schleicher

GmbH & Co.

P.A.K i.A.

P. Anklam

This Technical Note bases on a change, which was approved by EASA under the minor change approval EASA 10060932.