

# Summary of Airworthiness Directives (AD) and Technical Notes (TN)

## ALEXANDER SCHLEICHER

GMBH & CO

Segelflugzeugbau  
D-36163 Poppenhausen

Type: **ASW 27 -18 (ASG 29)** Data Sheet No.: **EASA.A.220**

Sheet: **1 of 2**

License: **DE.21G.0010**

| TN-No.               | AD-No.<br>Date of Issue | TN<br>Date of Issue                     | Affected Production Series<br>and Serial No.'s                                 | Subject  | Compliance  | Inspector's<br>stamp |
|----------------------|-------------------------|---|--|--|---|----------------------|
| <b>1</b>             | /                       | <b>28.02.07</b>                         | all ASW 27-18, prepared during production for engine installation (engine bay) | Conversion of the sailplane ASG 29 (Type Certificate EASA.A.220) into a powered sailplane ASG 29 E according to the same Type Certificate  | optional  |                      |
| <b>2</b>             | /                       | <b>30.01.09</b><br>EASA-appr.: 16.03.09 | all ASW 27-18  | Installation of a PCB-transponder antenna in the vertical tail.  | none,<br>optional on customer's request,<br>primarily on new production |                      |
| <b>3</b>             | /                       | <b>01.03.11</b><br>EASA-appr.: 01.04.11 | all ASW 27-18  | Installation of a strobe light in the nose of the vertical fin   | none,<br>optional on customer's request                                 |                      |
| <b>4</b>             | /                       | <b>01.03.11</b><br>EASA-appr.: 23.03.11 | all ASW 27-18  | Installation of a cockpit vent behind the canopy frame   | none,<br>optional on customer's request                                 |                      |
| <b>5</b>             |                         |   |  | intentionally left blank   |   |                      |
| <b>6</b>             | /                       | <b>20.11.15</b><br>EASA-appr.: 18.04.16 | all ASW 27-18  | A) Installation of a tail wheel cover<br>B) Installation of covers on the rudder<br>C) Replacement of the covers on the aileron and flap actuators<br>D) Modification of the blow hole system, Maintenance Instruction B Issue 2 | none,<br>optional on customer's request                                 |                      |
| <b>7</b><br>Issue II | /                       | <b>12.06.24</b><br>EASA-appr.: 08.02.18 | all ASW 27-18  | Alternative hydraulic wheel brake system TOST  | none,<br>optional on customer's request                                 |                      |
| <b>8</b>             | /                       | <b>07.11.19</b><br>EASA-appr.: 18.08.11 | all ASW 27-18  | Alternative rim for main wheel   | none,<br>optional on customer's request                                 |                      |

# Summary of Airworthiness Directives (AD) and Technical Notes (TN)

**ALEXANDER SCHLEICHER**

GMBH & CO

Segelflugzeugbau

D-36163 Poppenhausen

Type: **ASW 27 -18 (ASG 29)** Data Sheet No.: **EASA.A.220**

Sheet: **2 of 2**

License: **DE.21G.0010**

| TN-No.   | AD-No.<br>Date of Issue | TN<br>Date of Issue                     | Affected Production Series<br>and Serial No.'s | Subject  | Compliance                              | Inspector's<br>stamp |
|----------|-------------------------|---|--|--|---|----------------------|
| <b>9</b> | /                       | <b>03.04.20</b><br>EASA-appr.: 07.09.20 | all ASW 27-18                                  | Specification of service life limitations for the brake hoses of the hydraulic wheel brake | none,<br>optional on customer's request |                      |